



Fig. 1 – Tantalum screen with additional steel plate before test



Fig. 2 - Tantalum screen with additional steel plate after test (view from the site of steel plate)



Fig. 3 – View of test section after test (thermal screen and top parts of plasmatrons have been removed)



Fig. 4 – View of test section after test (fragmented debris bed and plasmatrons nozzles have been removed)



Fig. 5 – View of stainless steel housing outside graphite felt on the outer surface of RPV model



Fig 6 – View of RPV model outer surface (graphite felt has been removed)



Fig. 7 – Fragment of corium ingot (view from the surface contacted with RPV model wall)



Fig. 8 – View of RPV model with corium ingot adhered to the RPV model wall
(will be cut along the red line)